

40AF

10A 20

MT-32/2H□S -

MT-32/3H□S -

MT-32/3K□S MT-32/3D□S

Screw clamp

Screw clamp

Screw clamp

3

690V

Up to 690V

6kV

IP 20

-5--+40°C

■

■

■

■

0.1-40A

1-40A

0.1-0.16

0.16-0.25

0.25-0.4

0.4-0.63

0.63-1

1-1.6 1-1.6

1.6-2.5 1.6-2.5

2.5-4 2.5-4

4-6 4-6

5-8 5-8

6-9 6-9

7-10 7-10

9-13 9-13

12-18 12-18

16-22 16-22

18-25 18-25

22-32 22-32

- -

28-40 28-40

MC-9b, 12b, 18b, 22b, 32a, 40a

UZ-32

65AF

10A 20

MT-63/2H□S/L -

MT-63/3H□S/L -

MT-63/3K□S/L MT-63/3D□S/L

Screw/Lug clamp

Screw/Lug clamp

Screw clamp

3

690V

Up to 690V

6kV

IP 20

-5--+40°C

■

■

■

■

4-65A

4-6

4-6

5-8

5-8

6-9

6-9

7-10

7-10

9-13

9-13

12-18

12-18

16-22

16-22

18-25

18-25

-

-

24-36

24-36

28-40

28-40

34-50

34-50

45-65

45-65

MC-50a, 65a

UZ-63S/L

100AF

10A 20

MT-95/2H□S/L -

MT-95/3H□S/L -

MT-95/3K□S/L MT-95/3D□S/L

Screw/Lug clamp

Screw/Lug clamp

Screw clamp

3

690V

Up to 690V

6kV

IP 20

-5--+40°C

■

■

■

■

7-100A

7-10

7-10

9-13

9-13

12-18

12-18

16-22

16-22

18-25

18-25

-

-

24-36

24-36

28-40

28-40

34-50

34-50

45-65

45-65

54-75

54-75

63-85

63-85

70-95

70-95

80-100

80-100

MC-75a, 85a, 100a

UZ-95S/L